Issued to:	
APOLLO CRADLES LTD	
428 CARLTON ROAD	
CARLTON	
BARNSLEY	

Location of equipment:	
APOLLO CRADLES LTD	
428 CARLTON ROAD	
CARLTON	
BARNSLEY	

S71 3HX

Issue	d by:
	Lloyds British a division of
	Speedy Asset Services Ltd
	Brunel Industrial Estate
	Blyth Road
	Harworth
	DN11 8QA
Tal·	01709 386610



Report no:	2050/2468A
Your Order no:	TBA
Our Job no:	276676
Sheet no:	1 of 1

Report of Test and Thorough Examination of Lifting Plant and Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998, SI 2307

				Details of Test	t and Thorough Examination	
Identification Mark of the Equipment:	Description of Equipment	Qty Tested and Examined:	Safe Working Load: (Specify Units)	Proof Load Applied: (Specify Units)	Additional/Examination/Standards	Date of Test and Examination:
33958	2MTR APPOLLO X-BEAM FRAME	1	1000 KG	2000 KG	DEFLECTION RECORDED	05/06/17
_# (0 _# (6 (0) (0) (0)	WITH 2 ½ " FIXING TUBE ATTTACHED	-			SEE REPORT 2050/2461A1	
0 10 21						
					,	
	e)					
	*					
	*					
	· ·					

The above equipment has been thoroughly examined, no defects found and is safe to operate



S71 3HX

Name and address of person authenticating and signing this report on behalf of author:

Name:

STEVEN ENGLAND

Position:

TEST ENGINEER



Signature:

Date of Report:

5[™] JUNE 2017

Issued to:	
APOLLO CRADLES LTD	
428 CARLTON ROAD	
CARLTON	
BARNSLEY	
S71 3HX	

Location of equipment:	
APOLLO CRADLES LTD	
428 CARLTON ROAD	
CARLTON	
BARNSLEY	
S71 3HX	





Report no:	2050/2468B
Your Order no:	TBA
Our Job no:	276676
Sheet no:	1 of 1

Report of Test and Thorough Examination of Lifting Plant and Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998, SI 2307

* NO. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10				Details of Tes	t and Thorough Examination	
Identification Mark of the Equipment:	Description of Equipment	Qty Tested and Examined:	Safe Working Load: (Specify Units)	Proof Load Applied: (Specify Units)	Additional/Examination/Standards	Date of Test and Examination
33956	2MTR APPOLLO X-BEAM FRAME	1	1000 KG	2500 KG	DESTRUCTION TEST	05/06/17
	WITH 2 ½ " FIXING TUBE ATTTACHED			DESTRUCT		
	at the state of th					

The above equipment has been thoroughly examined, no defects found and is safe to operate



Name and address of person authenticating and signing this report on behalf of author:

Name:

STEVEN ENGLAND

Position:

TEST ENGINEER

LEEA

Signature:

Date of Report:

5TH JUNE 2017



TEST REPORT

ON aOI/TaOaaa	CHETOMED.	CHETOMED ODDED NO.
2050/2468A1	O O O O O O O O O O O O O O O O O O O	COOLOMEN ONDER INC.
276676	APOLLO CRADLES LTD	TBA
SUPPLIER:	DESCRIPTION:	DATE:
APOLLO CRADLES	2 MTR APPOLLO X BEAM	
428 CARLTON ROAD	ATTACHED	05/06/17
CARLTON,		
BARNSLEY		
S71 3HX		
ITEM	REPORT	-1
	LOAD APPLIED VERTICAL	DEFLECTION RETURNED ON
33958	DEFLECTION	RELEASE OF LOAD
	200 KG 2MM	YES
		YES
	600 KG 10MM	YES
	800 KG 14MM	YES
	1000 KG 16MM	YES
	1200 KG 19MM	YES
	1400 KG 24MM	NO
	1600 KG 26MM	NO
	1800 KG 28MM	NO
	2000 KG 32MM	NO
	2200 KG 34MM	NO
	2200 KG 38MM	NO
	-	NO
	2500 KG 42MM	NO

